IMPORTANT INSTALLATION NOTE

The DWA1000 Annunciator can not be installed in parallel with separate annunciator indicators unless external blocking diodes are installed. Refer to wiring example below. Recommended blocking diode –

Fairchild SB380

WARNING FAILURE TO INSTALL AN EXTERNAL BLOCKING DIODE TO SIGNAL WIRES WITH PARALLEL ANNUNCIATOR CONNECTIONS WILL DAMAGE THE UNIT.

